

Registration Certificate

This is to certify that the following company:

ROYAL WOOD FACTORY-SOLE PROPREITORSHIP L.L.C.

P.O. Box 38358, MW-5, 25A, Mussafah Industrial Area, Abu Dhabi,

United Arab Emirates

has successfully passed

Conformity Certification Services
Q-Plus Product Conformity Certification
For Fire Door Scheme
Single Site Certification

Tested as per the following Standard(s)

BS 476 Part 22:1987 Amd. 2014,

BS EN 1634-1:2014+A1:2018

Product Type: Doorset

Certificate No.: PC 202
Document ID: ROYA070419

07 APRIL 2019

Date of Initial Registration

13 MAY 2025
Date of Last Issue

06 APRIL 2030

Certificate Expiry Date

Signed on behalf of Conformity Certification Services

This certificate remains the property of Conformity Certification Services to whom it must be returned on request. Further clarification concerning to the validity, scope and verification of the certificate is accessible via scanning the barcode.

Conformity Certification Services
Office 1002, Al Saheel Tower 1, Al Nahda 1, Dubai, United Arab Emirates
Tel. 042399644 Email. info@ccs-certification.com
PC16-QP-ME-F01.1/Issue 8/February 2024









APPENDIX



Main Certification Holder

Address

ROYAL WOOD FACTORY-SOLE PROPREITORSHIP L.L.C.

P.O. Box 38358, MW-5, 25 A, Mussafah Industrial Area, Abu Dhabi, **United Arab Emirates**

Scope Details:

ocopo a cominer				/
Test Report ref.	Product Description	Tested Result		Test
	· ·	Integrity	Insulation	Standard
ML/ FRR-1903/9822	RoyalWood_Latched Single Acting, Steel Framed Single	60 minutes	60 minutes	BS 476
SN 1/1 (190311628)	Wooden Leaf Doorset with or without Vision Panel_FireBan			Part 22:1987
	Core 60_Non-Load Bearing Assembly			Amd.2014
ML/ FRR-1930/3500	RoyalWood_Latched Single Acting, Steel Framed Double	60 minutes	60 minutes	BS 476
C1-2 SN 1/1	Wooden Leaf Doorset with or without Vision Panel_FireBan			Part 22:1987
(190228624)	Core 60_Non-Load Bearing Assembly			Amd.2014
ML/TPWR-1803/4643	RoyalWood_Latched Single Acting, Double Leaf Wooden	60 minutes	60 minutes	BS 476
C1-2 SN 1/1	Doorset with or without Vision Panel_FireBan Core 60_Non-			Part 22:1987
(180313585)	Load Bearing Assembly			Amd.2014
	Y			
ML/518164 C1-2 SN 1/1	RoyalWood_Specimen 1_Latched Single Acting, Single Leaf	60 minutes	60 minutes	BS 476
(161107374)	Wooden Doorset with or without Vision Panel_FireBan Core			Part 22:1987
	60_Non-Load Bearing Assembly			Amd.2014
ML/518164 C1-2 SN 1/1	RoyalWood_Specimen 2_Latched Single Acting, Single Leaf	60 minutes	60 minutes	BS 476
(161107374)	Wooden Doo <mark>rset w</mark> ith or without Vision Panel_FireBan Core			Part 22:1987
	60_Non-Load Bearing Assembly			Amd.2014
ML/ FRR-1903/3501	RoyalWood_Latched Single Acting, Steel Framed Double	90 minutes	90 minutes	BS 476
C1-2 SN 1/1	Wooden Leaf Doorset with or without Vision Panel_FireBan	1		Part 22:1987
(190307626)	Core 90_Non-Load Bearing Assembly			Amd.2014
ML/ FRR-1903/9822	RoyalWood_Latched Single Acting, Steel Framed Single	90 minutes	90 minutes	BS 476
SN 1/1 (190311628)	Wooden Leaf Doorset with Vision Panel_FireBan Composite			Part 22:1987
	Core 90_Non-Load Bearing Assembly			Amd.2014
ML/517480 C1-2 SN 1/1	Roy <mark>alWood_Latched Single Acting, Single Leaf Wooden</mark>	90 minutes	90 minutes	BS 476
(161102371)	Doo <mark>rset with or without Vision Panel_FireBan Core 90_Non</mark> -			Part 22:1987
	Load Bearing Assembly			Amd.2014
ML/TPWR 1803/4642	RoyalWood_Latched Single Acting, Double Leaf Wooden	90 minutes	90 minutes	BS 476
C1-2 SN 1/1	Doorset with or without Vision Panel_FireBan Core 90_Non-			Part 22:1987
(180313584)	Load Bearing Assembly			Amd.2014

No alterations shall be made to any product specifications or parameters mentioned in the test report such as design, components, performance criteria without prior approval from CCS. Any violation of this requirement will invalidate existing test reports and certification approvals.

Test reports shall not be combined with primary FoA reports. It is crucial to follow the test reports precisely to ensure accurate results and reliable product performance.



Cont'd Certificate ID PC 202

Scope Details:

Test Report Ref.	Product Description	Tested Results/Properties		Test
		Integrity	Insulation	Standard
ML/ FRR-1709/3383A	RoyalWood_Latched Single Acting, Wooden Framed	120 minutes	120 minutes	BS 476
C1-2 SN 1/1 (170906521)	Double Composite Leaf Doorset with or without Vision			Part 22:1987
	Panel_FireBan Composite Core 120_Non Load Bearing Assembly			Amd.2014
ML/517480 C1-2 SN 1/1	RoyalWood_Latched Single Acting, Wooden Framed Single	120 minutes	120 minutes	BS 476
(161102371	Composite Leaf Doorset with or without Vision			Part 22:1987
	Panel_FireBan Composite Core 120_Non-Load Bearing Assembly			Amd.2014
ML/ FRR-2005/2187 A	RoyalWood_Unlatched, Double Acting, Double Leaf	60 minutes	60 minutes	EN 1634-1:
C1-2 (200510775)	Wooden Doorset with or without Vision Panel_64mm		1	2014 + A1:
	thick FireBan Core 90_Non-Load Bearing Assembly			2018
ML/FRR-2301/3727	Royal Wood_Latched, Single Acting, Single Leaf Wooden	60 minutes	60 minutes	BS 476
SN1/2 (2301061039)	Doorset with or without Vision Panel_54mm thick FireBAN			Part 22:1987
	Core 60_Non-Load Bearing Assembly			Amd. 2014

- No alterations shall be made to any product specifications or parameters mentioned in the test report such as design, components, performance criteria without prior approval from CCS. Any violation of this requirement will invalidate existing test reports and certification approvals.

 Test reports shall not be combined with primary FoA reports. It is crucial to follow the test reports precisely to ensure accurate results and reliable product performance.



CERTIFICATION EXPIRY DATE: 06 APRIL 2030 Conformity Certification Services Office 1002, Al Saheel Tower 1, Al Nahda 1, Dubai, United Arab Emirates
Tel. 042399644 Email. info@ccs-certification.com
PC16-QP-ME-F01.1/Issue 8/February 2024